



Milwaukee Pump

Technical Bulletin



Reference: 101414

Date: October 14, 2014

Product: D65, DP, E Series Pumps

Purpose: This bulletin advises Milwaukee Pump customers of crankshaft taper (cone) bearing compatibility issues.

Issue: Product revisions have resulted in changes to the pump crankshaft resulting in multiple tapered (cone) bearing part numbers and compatibility issues depending on the date of pump manufacture.

Solution: Milwaukee Pump Company *Tapered Roller Bearing Part # MP5674A18* is manufactured with a larger I.D. radius *that accommodates all current and past models of D65, DP and E-Series pumps* manufactured by Milwaukee Pump and F.E. Myers® regardless of the date of manufacture.